




Case Sleeve Case Stacker Assembly Instructions




Flat Parts




Completed assembly. Follow steps below and place display in desired location, then load with appropriate product




Step 1: Locate hutch and fold corner flap and corner tabs as shown.



Step 2: Fold four main panels around to to secure with corner tabs.



Step 3: Securely lock all corner tabs into slots on corner flap.



Step 4: Fold all four bottom flaps inward as shown.